



1/2-13 Thread X 1.0000" Depth Typical (2) Places For Fastening Standard Mounts To The Bolster Face.
(2) Standard Mounts Are Required Per Tray Support Platform And Can Be Located On 6.0000", 12.0000", Or 18.0000" Centers Using The Transfer Drill Template.

